

## Document Log Item

<b>Addressing</b>			
<b>From</b>		<b>To</b>	
"Christine Bucklin" <cbucklin@dtsc.ca.gov>		Carmen Santos/R9/USEPA/US@EPA	
<b>CC</b>		<b>BCC</b>	
<b>Description</b>		Form Used: Memo	
<b>Subject</b>		<b>Date/Time</b>	
Re: Pechiney Cast Plating site - PCBS		03/02/2009 05:01 PM	
<b># of Attachments</b>	<b>Total Bytes</b>	<b>NPM</b>	<b>Contributor</b>
0	8,465		
<b>Processing</b>			
<b>Comments</b>			

Body

### Document Body

Ms. Santos:

Is Max's email address his name ? like weintraub.max ?

what if they cannot determine the PCB concentration in the oil?

Looking forward to our discussion on March 5th.

Cheers

>>> <Santos.Carmen@epamail.epa.gov> 03/02/09 4:34 PM >>>

Greetings, Christine:

Thank you for your message. Please send electronic copies of the

information sent to Max Weintraub. I can make a conference call on March 5. I will let you know on March 3 what times I have available. I still need to know the PCB concentration in the oil that was used. Lets assume for now that TSCA applies to the soil cleanup as well as to the disposition of PCB containing concrete. I need more information as I explained earlier to let you know which cleanup options under TSCA is most appropriate for the site. I cannot answer your question with the extremely limited information included in your message.

I look forward to providing assistance on the Pechiney Cast Plating site.  
Thank you.

Regards,  
Carmen

Carmen D. Santos, Project Manager  
RCRA Corrective Action Office  
Waste Management Division  
USEPA Region 9  
415.972.3360  
fax: 415.947.3533

From:  
"Christine Bucklin" <cbucklin@dtsc.ca.gov>  
To:  
Carmen Santos/R9/USEPA/US@EPA  
Date:  
03/02/2009 04:12 PM

Subject:  
Pechiney Cast Plating site - PCBS

Ms. Santos,

We spoke on the phone this morning regarding my project in the City of Vernon. I also spoke with the consultant and she stated that they did briefly work with a Max Weintraub (sp.) from your offices, but that he let them know of the reorganization your groups were going through. They did send him a risk assessment and remedial action plan but they never received any response. She confirmed to me that the site has been operating since the early 30s and that the lubricating oils they utilized in the process of making the aluminum casts is the likely suspect. They do not have any information on the concentration of the PCBs in the oils. However, they know that the name of the oil is 'Pydrol' and that there were varying degrees, such as A, B, C, D etc.... the facility stopped using the oils and is out of business so, we don't know...in any case, leaks are likely ongoing since the facility operated.

PCBs in soil and concrete are characterized at the site. We would like to work with you to determine if the facility needs to have one of the 2 types of approvals that you mentioned. The consultant can make a phone

conference on Wednesday if you want to ask more questions, and she can send you the electronic copy of the document.

Please let me know what you think, thanking you in advance,

Christine Bucklin, P.G.  
Department of Toxic Substances Control  
Brownfields and Environmental Restoration Program  
9211 Oakdale Avenue  
Chatsworth, CA 91311  
OFFICE: (818)-717-6599  
FAX: (818) 717-6587